DISPLAY STANDSLtd

4 Crate Display Unit (CRATE/1) 4 Crate Display Unit (CRATE/H1)

PARTS SUPPLIED: 3 x Premium Crates 1 x Base Crate (with Wheels if selected) 1 2 3 4 9 x Joining Bolts 2 x Allen Keys Step 2. Step 1. Place Crate 3 on top of Place the base crate (with wheels) on the floor on it's side so you can access Crate 2 ensuring the drill the drill holes on the top. holes line up. Thread the 3 joining bolts through Thread the joining bolts Crate 3 into Crate 2 and through Crate 2 and tighten with allen keys into the top of Crate 1. provided. Tighten with allen keys provided and then stand the crates upright (as shown >>). Step 3. Step 4. Your crate display is Place Crate 4 on top of ready! Release the Crate 3 ensuring the drill holes line up. Thread the braked wheels to move Δ joining bolts through into position and place your products. Crate 4 into Crate 3 and tighten with allen keys provided.

www.display-stands-uk.com / 023 92 632 633